

Fitting Guide For Panel Replacement On Holibobs Cot

To be carried out by qualified and experienced personnel only

Failure to clamp securely directly across either side of barrel nut will allow movement and potentially damage the side panel



1



2



3



4



5



6



7



8



9

These bolts must be checked periodically to ensure the fixings are secure